

# Manhole Inspection Summary

Manhole # S43EE\_066MH

Printed On: 9/30/2009

Page 1 of 3

**Inspection** ☒ **Is Incomplete** Rating: **3) Fair**

Record Plat: **43EE** Node: **066** Status: **Found**

Insp Date: **9/8/09 1:26 PM**

Incomplete Comments

**Force Main Vault - Cannot Complete the Inspection Due to the Hazardous Condition**

Crew: **ADS2**  
Inspector: **ADS2**  
Firm: **ADS**

**Location** Address: **1050 BROADWAY**

Cross Street: **CHASE ST**

**Manhole**

Type:

Location: **Roadway**

Ground Conditions: **Dry**

☐ Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments **FORCE MAIN VAULT MH IS UNSAFE TO DIVE**

**Cover**

Shape:

Diameter: (in.)

Length: (in.)

Dist A/B Grade: (in.)

Type: **Sanitary**

Condition:

Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

**Frame**

Offset: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Leaks

**Chimney / Frame Adjustment**

☐ Exists

Material:

☐ Parged

Height: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Corbel**

Material:

☐ Parged

Type:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Barrel**

Material:

☐ Parged

Shape:

Diameter: (in.)

Length: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Bench**

☐ Exists Material:

☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Channel**

Material:

☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Steps**

Count:

Missing:

☐ Corroded

**Surcharge**

☐ Evidence Of Surcharge

Depth: (ft.)

☐ Active Surcharge Present

Location View



Top View



Top View



Top View



